

「染色堅牢度規格」

| 商品名 | 番手 | カラーナンバー | JIS L 0844(洗濯) A-2号 | | | JIS L 0842 (耐光 注1) | JIS L 0849(摩擦) | | JIS L 0848(汗・酸性・アルカリ性) | | | | | | JIS L 0846(水) | | | JIS L 0888(汗・耐光複合) B法 | | |
|-----------|------|---------|---------------------|-------|-------|-----------------------|----------------|-----|------------------------|-------|-------|-------|-------|-------|---------------|-------|-------|-----------------------|------------|-----|
| | | | 変退色 | 汚染(綿) | 汚染(絹) | | 乾燥 | 洗濯 | 酸性 | | | アルカリ性 | | | 変退色 | 汚染(綿) | 汚染(絹) | 変退色(酸性) | 変退色(アルカリ性) | |
| | | | | | | | | | 変退色 | 汚染(綿) | 汚染(絹) | 変退色 | 汚染(綿) | 汚染(絹) | | | | | | |
| T/C 50/50 | 30/1 | S1 | 4-5 | 4-5 | 4-5 | 4 | 5 | 3 | 4-5 | 4-5 | 4-5 | 4-5 | 4-5 | 4-5 | 4-5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 |
| T/C 50/50 | 30/1 | S2 | 5 | 5 | 5 | 4 | 4-5 | 2-3 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 5 | 5 | 4-5 | 4-5 | 4-5 |
| T/C 50/50 | 30/1 | W3 | 4-5 | 4-5 | 4-5 | 3 | 4-5 | 4-5 | 4-5 | 4-5 | 4-5 | 4-5 | 4-5 | 4-5 | 4-5 | 4-5 | 4 | 4-5 | 5 | 5 |
| T/C 50/50 | 30/1 | S4 | 5 | 4 | 4 | 4 | 4-5 | 2 | 5 | 4 | 4 | 5 | 4 | 4 | 5 | 4 | 5 | 4 | 5 | 5 |
| T/C 50/50 | 30/1 | S5 | 5 | 4-5 | 4-5 | 4 | 4-5 | 2-3 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 |
| T/C 50/50 | 30/1 | L6 | 4-5 | 4-5 | 4-5 | 4 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 4-5 |
| T/C 50/50 | 30/1 | M7 | 4-5 | 4-5 | 4-5 | 4 | 5 | 4-5 | 4-5 | 5 | 5 | 4-5 | 5 | 5 | 4-5 | 5 | 5 | 5 | 5 | 5 |
| T/C 50/50 | 30/1 | M8 | 5 | 4-5 | 4-5 | 4 | 5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 4-5 | 5 | 5 |
| T/C 50/50 | 30/1 | M9 | 4-5 | 4-5 | 4-5 | 4 | 5 | 4 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 5 | 5 |
| T/C 50/50 | 30/1 | L11 | 4-5 | 4-5 | 4-5 | 4 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 |
| T/C 50/50 | 30/1 | L12 | 4-5 | 4-5 | 4-5 | 4 | 5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 5 | 5 |
| T/C 50/50 | 30/1 | L13 | 5 | 5 | 5 | 4 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 |
| T/C 50/50 | 30/1 | L14 | 4-5 | 4-5 | 4-5 | 4 | 5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 5 | 5 |
| T/C 50/50 | 30/1 | S15 | 4-5 | 4-5 | 4-5 | 4 | 4 | 2-3 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 5 | 5 |
| T/C 50/50 | 30/1 | M17 | 5 | 4-5 | 4-5 | 4 | 4-5 | 4 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 5 | 5 |
| T/C 50/50 | 30/1 | M18 | 4-5 | 4-5 | 4-5 | 4 | 5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 5 | 5 |
| T/C 50/50 | 30/1 | M19 | 5 | 4-5 | 4-5 | 4 | 5 | 3-4 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 5 | 5 |
| T/C 50/50 | 30/1 | M20 | 4-5 | 4-5 | 4-5 | 4 | 5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 4-5 | 4-5 | 3-4 |
| T/C 50/50 | 30/1 | D21 | 5 | 4-5 | 4-5 | 4 | 5 | 4 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 4-5 | 4-5 | 3-4 |
| T/C 50/50 | 30/1 | M22 | 4-5 | 5 | 5 | 4 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 4-5 | 3-4 |
| T/C 50/50 | 30/1 | S23 | 4-5 | 4-5 | 4-5 | 4 | 4-5 | 3 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 4-5 | 4-5 | 4-5 |
| T/C 50/50 | 30/1 | S24 | 4-5 | 4-5 | 4-5 | 4 | 4-5 | 3-4 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 4-5 | 4-5 | 4-5 |
| T/C 50/50 | 30/1 | L25 | 5 | 5 | 5 | 4 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 |
| T/C 50/50 | 30/1 | S26 | 4-5 | 4-5 | 4-5 | 4 | 4-5 | 3 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 5 | 5 |
| T/C 50/50 | 30/1 | S27 | 5 | 4-5 | 4-5 | 4 | 5 | 4 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 |
| T/C 50/50 | 30/1 | S28 | 4-5 | 4 | 4 | 4 | 5 | 3 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 |
| T/C 50/50 | 30/1 | D30 | 5 | 5 | 5 | 4 | 5 | 3-4 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 4-5 | 4-5 |
| T/C 50/50 | 30/1 | S31 | 5 | 4-5 | 4-5 | 4 | 4-5 | 3 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 |
| T/C 50/50 | 30/1 | M32 | 5 | 4-5 | 4-5 | 4 | 5 | 5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 4-5 | 4-5 | 4-5 |
| T/C 50/50 | 30/1 | M33 | 5 | 4-5 | 4-5 | 4 | 4-5 | 3-4 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 4-5 | 4-5 | 4-5 |
| T/C 50/50 | 30/1 | M34 | 4-5 | 4-5 | 4-5 | 4 | 5 | 4-5 | 5 | 5 | 5 | 5 | 5 | 5 | 4-5 | 4-5 | 4-5 | 5 | 5 | 5 |
| T/C 50/50 | 30/1 | D35 | 4-5 | 4-5 | 4-5 | 4 | 5 | 4 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 4-5 | 4-5 | 4 |
| T/C 50/50 | 30/1 | S36 | 4-5 | 4-5 | 4-5 | 4 | 4-5 | 3 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 |
| T/C 50/50 | 30/1 | S37 | 4-5 | 4-5 | 4-5 | 4 | 5 | 3-4 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 4-5 | 4-5 | 4-5 |
| T/C 50/50 | 30/1 | S38 | 5 | 4-5 | 4-5 | 4 | 4-5 | 2-3 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 4-5 | 4-5 | 4-5 |
| T/C 50/50 | 30/1 | M39 | 4-5 | 4-5 | 4-5 | 4 | 5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 5 | 5 |
| T/C 50/50 | 30/1 | M40 | 4-5 | 5 | 5 | 4 | 5 | 4-5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 4-5 | 4-5 |
| T/C 50/50 | 30/1 | M41 | 4-5 | 5 | 5 | 4 | 5 | 4-5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 4-5 | 4-5 |
| T/C 50/50 | 30/1 | S42 | 5 | 4-5 | 4-5 | 4 | 5 | 3 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 4-5 | 4-5 | 4-5 |
| T/C 50/50 | 30/1 | M43 | 4-5 | 4-5 | 4-5 | 4 | 5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 |
| T/C 50/50 | 30/1 | L45 | 4-5 | 4-5 | 4-5 | 4 | 5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 4-5 | 4-5 | 4-5 |
| T/C 50/50 | 30/1 | M46 | 4-5 | 4-5 | 4-5 | 4 | 5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 4-5 | 4-5 | 4-5 |
| T/C 50/50 | 30/1 | D49 | 5 | 4-5 | 4-5 | 4 | 5 | 3-4 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 5 | 5 |
| T/C 50/50 | 30/1 | D50 | 5 | 4 | 4 | 4 | 5 | 3 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 4-5 | 4-5 |
| T/C 50/50 | 30/1 | M51 | 5 | 4-5 | 4-5 | 4 | 5 | 4 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 4-5 | 4-5 | 4-5 |
| T/C 50/50 | 30/1 | S52 | 5 | 4-5 | 4-5 | 4 | 5 | 3-4 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 5 | 5 |
| T/C 50/50 | 30/1 | L53 | 4-5 | 5 | 5 | 4 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 |
| T/C 50/50 | 30/1 | M54 | 4-5 | 4-5 | 4-5 | 4 | 5 | 4-5 | 4-5 | 4-5 | 4-5 | 4-5 | 4-5 | 4-5 | 4-5 | 4-5 | 4-5 | 4-5 | 4-5 | 5 |
| T/C 50/50 | 30/1 | S59 | 4-5 | 4-5 | 4-5 | 4 | 5 | 3 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 5 | 5 |
| T/C 50/50 | 30/1 | M61 | 4-5 | 4-5 | 4-5 | 4 | 4-5 | 4 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 5 | 5 |
| T/C 50/50 | 30/1 | S62 | 4-5 | 4-5 | 4-5 | 4 | 4-5 | 3-4 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 |
| T/C 50/50 | 30/1 | M64 | 5 | 5 | 5 | 4 | 5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 |
| T/C 50/50 | 30/1 | M65 | 4-5 | 4-5 | 4-5 | 4 | 5 | 5 | 4-5 | 5 | 5 | 4-5 | 5 | 5 | 4-5 | 5 | 5 | 5 | 4-5 | 4-5 |
| T/C 50/50 | 30/1 | M67 | 4-5 | 4-5 | 4-5 | 4 | 5 | 4-5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 4-5 | 3 |
| T/C 50/50 | 30/1 | D68 | 4-5 | 4-5 | 4-5 | 4 | 4-5 | 3-4 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 |
| T/C 50/50 | 30/1 | M70 | 4-5 | 4-5 | 4-5 | 4 | 5 | 4 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 |
| T/C 50/50 | 30/1 | M71 | 4-5 | 4-5 | 4-5 | 4 | 5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 5 |
| T/C 50/50 | 30/1 | M72 | 4-5 | 5 | 5 | 4 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 |
| T/C 50/50 | 30/1 | L73 | 4-5 | 4-5 | 4-5 | 4 | 5 | 5 | 4-5 | 5 | 5 | 4-5 | 5 | 5 | 4-5 | 5 | 5 | 5 | 5 | 5 |
| T/C 50/50 | 30/1 | L74 | 4-5 | 4-5 | 4-5 | 4 | 5 | 4-5 | 4-5 | 4-5 | 4-5 | 4-5 | 4-5 | 4-5 | 4-5 | 4-5 | 4-5 | 5 | 5 | 5 |
| T/C 50/50 | 30/1 | D75 | 4-5 | 4-5 | 4-5 | 4 | 5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 |
| T/C 50/50 | 30/1 | S76 | 4-5 | 4-5 | 4-5 | 4 | 5 | 4 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4 |
| T/C 50/50 | 30/1 | M78 | 5 | 5 | 5 | 4 | 5 | 4-5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 4-5 | 4-5 |
| T/C 50/50 | 30/1 | S79 | 5 | 4-5 | 4-5 | 4 | 5 | 3-4 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 5 | 5 |
| T/C 50/50 | 30/1 | M80 | 5 | 4-5 | 4-5 | 4 | 5 | 4 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 4-5 | 4-5 |
| T/C 50/50 | 30/1 | M81 | 4-5 | 4-5 | 4-5 | 4 | 5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4 | 4 |
| T/C 50/50 | 30/1 | S82 | 4-5 | 4-5 | 4-5 | 4 | 5 | 3 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4 |
| T/C 50/50 | 30/1 | S83 | 4-5 | 4-5 | 4-5 | 4 | 5 | 3-4 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 |
| T/C 50/50 | 30/1 | M84 | 5 | 4-5 | 4-5 | 4 | 5 | 3-4 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4 | 4 |
| T/C 50/50 | 30/1 | S86 | 4-5 | 4-5 | 4-5 | 4 | 4-5 | 3 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 5 | 5 |
| T/C 50/50 | 30/1 | S87 | 4-5 | 4-5 | 4-5 | 4 | 4-5 | 3-4 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 5 |
| T/C 50/50 | 30/1 | L88 | 4-5 | 4-5 | 4-5 | 4 | 5 | 5 | 4-5 | 5 | 5 | 4-5 | 5 | 5 | 4-5 | 5 | 5 | 5 | 5 | 5 |

| 商品名 | 番手 | カラーナンバー | JIS L 0844(洗濯) A-2号 | | | JIS L 0842 (耐光 注1) | JIS L 0849(摩擦) | | JIS L 0848(汗・酸性・アルカリ性) | | | | | | JIS L 0846(水) | | | JIS L 0888(汗・耐光複合) B法 | | | |
|-----------|------|---------|---------------------|-------|-------|-----------------------|----------------|-----|------------------------|-------|-------|-------|-------|-------|---------------|-------|-------|-----------------------|------------|-----|-----|
| | | | 変退色 | 汚染(綿) | 汚染(絹) | | 乾燥 | 湿潤 | 酸性 | | | アルカリ性 | | | 変退色 | 汚染(綿) | 汚染(絹) | 変退色(酸性) | 変退色(アルカリ性) | | |
| | | | | | | | | | 変退色 | 汚染(綿) | 汚染(絹) | 変退色 | 汚染(綿) | 汚染(絹) | | | | | | | |
| T/C 50/50 | 30/1 | L223 | 5 | 5 | 5 | 4 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 |
| T/C 50/50 | 30/1 | L224 | 4-5 | 4-5 | 4-5 | 4 | 4-5 | 4-5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 |
| T/C 50/50 | 30/1 | M226 | 4-5 | 4-5 | 4-5 | 4 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 5 | 5 |
| T/C 50/50 | 30/1 | M227 | 5 | 4-5 | 4-5 | 4 | 5 | 3-4 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 5 | 5 |
| T/C 50/50 | 30/1 | D228 | 4-5 | 4-5 | 4-5 | 4 | 4-5 | 3-4 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 5 | 5 |
| T/C 50/50 | 30/1 | L230 | 4-5 | 4-5 | 4-5 | 4 | 5 | 4-5 | 4-5 | 4-5 | 4-5 | 4-5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 5 | 5 |
| T/C 50/50 | 30/1 | S231 | 5 | 4-5 | 4-5 | 4 | 5 | 3 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 5 | 5 |
| T/C 50/50 | 30/1 | S232 | 4-5 | 4-5 | 4-5 | 4 | 4-5 | 2-3 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 5 | 5 |
| T/C 50/50 | 30/1 | D233 | 5 | 4-5 | 4-5 | 4 | 5 | 3-4 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 5 | 5 |
| T/C 50/50 | 30/1 | D234 | 4-5 | 4-5 | 4-5 | 4 | 4-5 | 3 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 5 | 5 |
| T/C 50/50 | 30/1 | L236 | 4-5 | 4-5 | 4-5 | 4 | 5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 5 | 4-5 |
| T/C 50/50 | 30/1 | D238 | 4-5 | 4-5 | 4-5 | 4 | 5 | 4 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 5 | 5 |
| T/C 50/50 | 30/1 | L240 | 4-5 | 4-5 | 4-5 | 4 | 5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 5 | 5 |
| T/C 50/50 | 30/1 | L241 | 4-5 | 4-5 | 4-5 | 4 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 |
| T/C 50/50 | 30/1 | M242 | 4-5 | 4-5 | 4-5 | 4 | 5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 4-5 | 4-5 | 4-5 | 4-5 |
| T/C 50/50 | 30/1 | L243 | 5 | 5 | 5 | 4 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 |
| T/C 50/50 | 30/1 | M244 | 4-5 | 4-5 | 4-5 | 4 | 5 | 5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 5 | 5 |
| T/C 50/50 | 30/1 | M245 | 4-5 | 4-5 | 4-5 | 4 | 5 | 4 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 5 | 3-4 |
| T/C 50/50 | 30/1 | S247 | 4-5 | 4-5 | 4-5 | 4 | 4-5 | 3 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 5 | 5 |
| T/C 50/50 | 30/1 | S248 | 4-5 | 4 | 4 | 4 | 4-5 | 2-3 | 4-5 | 4 | 4 | 4-5 | 4 | 4 | 4-5 | 4 | 4 | 5 | 4-5 | 4 | 4-5 |
| T/C 50/50 | 30/1 | M249 | 4-5 | 4-5 | 4-5 | 4 | 5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 4-5 |
| T/C 50/50 | 30/1 | M250 | 4-5 | 4 | 4 | 4 | 4-5 | 3-4 | 4-5 | 4 | 4 | 4-5 | 4 | 4 | 4-5 | 4 | 4 | 5 | 4-5 | 4 | 4 |
| T/C 50/50 | 30/1 | M251 | 4-5 | 4-5 | 4-5 | 4 | 5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 4-5 |
| T/C 50/50 | 30/1 | D252 | 4-5 | 4-5 | 4-5 | 4 | 4-5 | 3 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 4-5 | 4-5 | 4-5 | 3-4 |
| T/C 50/50 | 30/1 | M253 | 5 | 5 | 5 | 4 | 5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 5 | 4-5 |
| T/C 50/50 | 30/1 | M254 | 5 | 5 | 5 | 4 | 5 | 4-5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 4-5 |
| T/C 50/50 | 30/1 | M255 | 4-5 | 4 | 4 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 |
| T/C 50/50 | 30/1 | M256 | 4-5 | 4-5 | 4-5 | 4 | 4-5 | 4 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 5 | 4-5 |
| T/C 50/50 | 30/1 | S257 | 4-5 | 4-5 | 4-5 | 4 | 4-5 | 2-3 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 5 | 4-5 |
| T/C 50/50 | 30/1 | M258 | 4-5 | 4-5 | 4-5 | 4 | 4-5 | 4 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 4-5 |
| T/C 50/50 | 30/1 | L259 | 5 | 5 | 5 | 4 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 |
| T/C 50/50 | 30/1 | M260 | 4-5 | 5 | 5 | 4 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 4-5 | 4-5 |
| T/C 50/50 | 30/1 | L261 | 4-5 | 4-5 | 4-5 | 4 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 5 | 4-5 |
| T/C 50/50 | 30/1 | M262 | 4-5 | 4-5 | 4-5 | 4 | 4-5 | 3-4 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 5 | 4-5 |
| T/C 50/50 | 30/1 | L266 | 4-5 | 4-5 | 4-5 | 4 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 4-5 |
| T/C 50/50 | 30/1 | M267 | 5 | 4-5 | 4-5 | 4 | 5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 5 | 4-5 |
| T/C 50/50 | 30/1 | D271 | 4-5 | 4-5 | 4-5 | 4 | 4-5 | 2-3 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 4-5 |
| T/C 50/50 | 30/1 | M272 | 5 | 4-5 | 4-5 | 4 | 5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 5 | 5 |
| T/C 50/50 | 30/1 | M274 | 4-5 | 4-5 | 4-5 | 4 | 4-5 | 4 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 4-5 |
| T/C 50/50 | 30/1 | M275 | 4-5 | 5 | 5 | 4 | 5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 5 | 4-5 |
| T/C 50/50 | 30/1 | M276 | 4-5 | 4-5 | 4-5 | 4 | 5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 4 |
| T/C 50/50 | 30/1 | D278 | 4-5 | 4-5 | 4-5 | 4 | 4-5 | 3-4 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 4-5 |
| T/C 50/50 | 30/1 | M279 | 4-5 | 4-5 | 4-5 | 4 | 5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 4-5 |
| T/C 50/50 | 30/1 | L281 | 4-5 | 4-5 | 4-5 | 4 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 4-5 |
| T/C 50/50 | 30/1 | D282 | 4-5 | 4 | 4 | 4 | 4-5 | 3 | 4-5 | 4 | 4 | 4-5 | 4 | 4 | 4-5 | 4 | 4 | 5 | 4-5 | 4 | 4 |
| T/C 50/50 | 30/1 | L283 | 4-5 | 4-5 | 4-5 | 4 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 4-5 |
| T/C 50/50 | 30/1 | D284 | 4-5 | 4-5 | 4-5 | 4 | 4-5 | 3 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 5 | 4-5 |
| T/C 50/50 | 30/1 | M285 | 4-5 | 4-5 | 4-5 | 4 | 5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 5 | 4-5 |
| T/C 50/50 | 30/1 | S286 | 5 | 4-5 | 4-5 | 4 | 5 | 3-4 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 5 | 5 | 5 | 4-5 | 5 | 3-4 |
| T/C 50/50 | 30/1 | M288 | 4-5 | 4-5 | 4-5 | 4 | 4-5 | 3-4 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 5 | 5 |
| T/C 50/50 | 30/1 | M289 | 4-5 | 4-5 | 4-5 | 4 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 5 | 4 |
| T/C 50/50 | 30/1 | M290 | 4-5 | 4-5 | 4-5 | 4 | 5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 5 | 5 |
| T/C 50/50 | 30/1 | M291 | 4-5 | 5 | 5 | 4 | 5 | 5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 4-5 |
| T/C 50/50 | 30/1 | M292 | 4-5 | 4-5 | 4-5 | 4 | 4-5 | 3-4 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 5 | 4 |
| T/C 50/50 | 30/1 | S294 | 4-5 | 4-5 | 4-5 | 4 | 4 | 2-3 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 5 | 4-5 |
| T/C 50/50 | 30/1 | L295 | 5 | 5 | 5 | 4 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 |
| T/C 50/50 | 30/1 | M296 | 4-5 | 4-5 | 4-5 | 4 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 4-5 |
| T/C 50/50 | 30/1 | S297 | 5 | 4 | 4 | 4 | 4 | 3 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 4-5 |
| T/C 50/50 | 30/1 | D298 | 4-5 | 4-5 | 4-5 | 4 | 5 | 3 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 4 |
| T/C 50/50 | 30/1 | L299 | 4-5 | 4-5 | 4-5 | 4 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 4-5 |
| T/C 50/50 | 30/1 | L300 | 4-5 | 4-5 | 4-5 | 4 | 5 | 4-5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 4-5 |
| T/C 50/50 | 30/1 | M301 | 4-5 | 4-5 | 4-5 | 4 | 5 | 5 | 4-5 | 4-5 | 4-5 | 4-5 | 4-5 | 4-5 | 4-5 | 4-5 | 4-5 | 5 | 4-5 | 4 | 3-4 |
| T/C 50/50 | 30/1 | M302 | 4-5 | 5 | 5 | 4 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 3-4 |
| T/C 50/50 | 30/1 | M303 | 4-5 | 4-5 | 4-5 | 4 | 5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 5 | 4-5 |
| T/C 50/50 | 30/1 | M304 | 4-5 | 4-5 | 4-5 | 4 | 5 | 4 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 5 | 3-4 |
| T/C 50/50 | 30/1 | D305 | 4-5 | 5 | 5 | 4 | 5 | 4 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 5 | 4-5 |
| T/C 50/50 | 30/1 | L306 | 4-5 | 4-5 | 4-5 | 4 | 5 | 5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 5 | 4-5 |
| T/C 50/50 | 30/1 | M307 | 4-5 | 4 | 4 | 4 | 4-5 | 4 | 4-5 | 4 | 4 | 4-5 | 4 | 4 | 4-5 | 4 | 4 | 4-5 | 4 | 4-5 | 3-4 |
| T/C 50/50 | 30/1 | W308 | 4-5 | 4-5 | 4-5 | 3 | 4-5 | 4-5 | 4-5 | 4-5 | 4-5 | 4-5 | 4-5 | 4-5 | 4-5 | 4-5 | 4-5 | 4-5 | 4-5 | 4-5 | 4-5 |
| T/C 50/50 | 30/1 | D309 | 4-5 | 4-5 | 4-5 | 4 | 4-5 | 3 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 5 | 4-5 |
| T/C 50/50 | 30/1 | M310 | 4-5 | 4 | 4 | 4 | 4-5 | 3-4 | 4-5 | 4-5 | 4-5 | 4-5 | 4-5 | 4-5 | 4-5 | 4-5 | 4-5 | 5 | 4-5 | 5 | 4-5 |
| T/C 50/50 | 30/1 | M311 | 5 | | | | | | | | | | | | | | | | | | |

「染色堅牢度規格」

| 商品名 | 番手 | カラーナンバー | JIS L 0844 (洗濯) A-2号 | | | JIS L 0842 (耐光 注1) | JIS L 0849 (摩擦) | | JIS L 0848 (汗・酸性・アルカリ性) | | | | | | JIS L 0846 (水) | | | JIS L 0888 (汗・耐光複合) B法 | | |
|-----------|------|---------|----------------------|--------|--------|-----------------------|-----------------|-----|-------------------------|--------|--------|-------|--------|--------|----------------|--------|--------|------------------------|-------------|-----|
| | | | 変退色 | 汚染 (綿) | 汚染 (絹) | | 乾燥 | 湿潤 | 酸性 | | | アルカリ性 | | | 変退色 | 汚染 (綿) | 汚染 (絹) | 変退色 (酸性) | 変退色 (アルカリ性) | |
| | | | | | | | | | 変退色 | 汚染 (綿) | 汚染 (絹) | 変退色 | 汚染 (綿) | 汚染 (絹) | | | | | | |
| T/C 50/50 | 30/1 | M312 | 4-5 | 4-5 | 4-5 | 4 | 5 | 4-5 | 5 | 4-5 | 5 | 5 | 4-5 | 5 | 4-5 | 5 | 4-5 | 5 | 4-5 | 4 |
| T/C 50/50 | 30/1 | M313 | 4-5 | 4-5 | 4-5 | 4 | 5 | 4-5 | 5 | 5 | 5 | 5 | 5 | 5 | 4-5 | 4-5 | 4-5 | 4-5 | 4-5 | 3-4 |
| T/C 50/50 | 30/1 | L314 | 4-5 | 4-5 | 4-5 | 4 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 5 | 5 |
| T/C 50/50 | 30/1 | L315 | 4-5 | 4-5 | 4-5 | 4 | 4-5 | 4-5 | 4-5 | 4-5 | 4-5 | 4-5 | 4-5 | 4-5 | 4-5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 |
| T/C 50/50 | 30/1 | D316 | 5 | 4-5 | 4-5 | 4 | 5 | 3-4 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 5 | 5 | 5 | 5 | 4-5 |
| T/C 50/50 | 30/1 | M317 | 4-5 | 5 | 5 | 4 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 4-5 |
| T/C 50/50 | 30/1 | D318 | 5 | 4 | 4 | 4 | 5 | 3 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 4-5 | 4-5 | 4-5 |
| T/C 50/50 | 30/1 | S319 | 4-5 | 4-5 | 4-5 | 4 | 4-5 | 3 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 5 | 5 |
| T/C 50/50 | 30/1 | D321 | 4-5 | 4-5 | 4-5 | 4 | 4-5 | 3-4 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 4-5 | 4-5 | 4-5 |
| T/C 50/50 | 30/1 | D322 | 5 | 4-5 | 4-5 | 4 | 5 | 4 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 5 | 4-5 |
| T/C 50/50 | 30/1 | S323 | 5 | 4-5 | 4-5 | 4 | 5 | 3 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 4-5 |
| T/C 50/50 | 30/1 | M324 | 5 | 5 | 5 | 4 | 5 | 4-5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 4-5 | 3-4 |
| T/C 50/50 | 30/1 | D325 | 4-5 | 4 | 4 | 4 | 4-5 | 3-4 | 4-5 | 4 | 4 | 4-5 | 4 | 4 | 4-5 | 4 | 4 | 5 | 4-5 | 4-5 |
| T/C 50/50 | 30/1 | D328 | 4-5 | 4-5 | 4-5 | 4 | 4-5 | 4 | 4-5 | 4 | 4 | 4-5 | 4 | 4 | 4-5 | 4 | 4-5 | 4-5 | 4-5 | 4-5 |
| T/C 50/50 | 30/1 | S330 | 5 | 4-5 | 4-5 | 4 | 5 | 3-4 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 4-5 | 4-5 | 4 |
| T/C 50/50 | 30/1 | M331 | 5 | 5 | 5 | 4 | 5 | 4-5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 4-5 |
| T/C 50/50 | 30/1 | L332 | 4-5 | 4-5 | 4-5 | 4 | 5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 5 | 5 |
| T/C 50/50 | 30/1 | M333 | 4-5 | 4-5 | 4-5 | 4 | 4-5 | 3 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 5 | 4-5 |
| T/C 50/50 | 30/1 | M334 | 4-5 | 4-5 | 4-5 | 4 | 5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 5 | 4-5 |
| T/C 50/50 | 30/1 | M336 | 4-5 | 4-5 | 4-5 | 4 | 4-5 | 4 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 5 | 4-5 |
| T/C 50/50 | 30/1 | M337 | 4-5 | 4-5 | 4-5 | 4 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 5 | 4-5 |
| T/C 50/50 | 30/1 | D341 | 5 | 4-5 | 4-5 | 4 | 5 | 3 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 |
| T/C 50/50 | 30/1 | D350 | 4-5 | 4-5 | 4-5 | 4 | 4 | 3 | 4-5 | 4 | 4 | 4-5 | 4 | 4 | 4-5 | 4 | 4-5 | 5 | 4-5 | 4-5 |
| T/C 50/50 | 30/1 | D351 | 4-5 | 4-5 | 4-5 | 4 | 5 | 5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 4-5 | 4-5 | 4-5 | 5 | 5 | 4-5 |
| T/C 50/50 | 30/1 | D362 | 4-5 | 4-5 | 4-5 | 4 | 4-5 | 3 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 4-5 | 4-5 | 5 |
| T/C 50/50 | 30/1 | M353 | 4-5 | 4-5 | 4-5 | 4 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 5 | 3-4 |
| T/C 50/50 | 30/1 | M354 | 4-5 | 4-5 | 4-5 | 4 | 4-5 | 4 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 5 | 4-5 |
| T/C 50/50 | 30/1 | L356 | 4-5 | 4-5 | 4-5 | 4 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 |
| T/C 50/50 | 30/1 | D357 | 4-5 | 4-5 | 4-5 | 4 | 4-5 | 3 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 4-5 | 4-5 | 4 |
| T/C 50/50 | 30/1 | L358 | 4-5 | 4-5 | 4-5 | 4 | 5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 4-5 | 4-5 | 4 |
| T/C 50/50 | 30/1 | M359 | 4-5 | 4-5 | 4-5 | 4 | 5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 5 | 4-5 |
| T/C 50/50 | 30/1 | M360 | 5 | 5 | 5 | 4 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 4-5 |
| T/C 50/50 | 30/1 | S361 | 4-5 | 4-5 | 4-5 | 4 | 4-5 | 3 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 5 | 4-5 |
| T/C 50/50 | 30/1 | S362 | 4-5 | 4 | 4 | 4 | 4-5 | 3 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 5 | 4-5 |
| T/C 50/50 | 30/1 | L363 | 5 | 5 | 5 | 4 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 3-4 |
| T/C 50/50 | 30/1 | M364 | 4-5 | 4-5 | 4-5 | 4 | 5 | 4-5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 |
| T/C 50/50 | 30/1 | M365 | 4-5 | 4-5 | 4-5 | 4 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 5 | 4 |
| T/C 50/50 | 30/1 | M366 | 5 | 4-5 | 4-5 | 4 | 5 | 5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 5 | 5 | 5 | 5 | 4-5 |
| T/C 50/50 | 30/1 | M367 | 4-5 | 4-5 | 4-5 | 4 | 5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 5 | 4-5 |
| T/C 50/50 | 30/1 | S368 | 4-5 | 4-5 | 4-5 | 4 | 5 | 2 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 5 | 5 |
| T/C 50/50 | 30/1 | M369 | 4-5 | 4-5 | 4-5 | 4 | 4-5 | 4 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 5 | 4-5 |
| T/C 50/50 | 30/1 | M370 | 4-5 | 4-5 | 4-5 | 4 | 4-5 | 4 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 5 | 4-5 |
| T/C 50/50 | 30/1 | M371 | 4-5 | 4-5 | 4-5 | 4 | 5 | 4 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 5 | 4-5 |
| T/C 50/50 | 30/1 | D372 | 5 | 4-5 | 4-5 | 4 | 5 | 4 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 4 |
| T/C 50/50 | 30/1 | M373 | 4-5 | 4-5 | 4-5 | 4 | 5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 4-5 | 4-5 | 4-5 |
| T/C 50/50 | 30/1 | D374 | 4-5 | 4-5 | 4-5 | 4 | 4-5 | 3-4 | 4-5 | 4 | 4 | 4-5 | 4 | 4 | 4-5 | 4 | 4 | 5 | 5 | 4-5 |
| T/C 50/50 | 30/1 | D375 | 4-5 | 4-5 | 4-5 | 4 | 5 | 3 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 5 | 4 |
| T/C 50/50 | 30/1 | S376 | 4-5 | 4-5 | 4-5 | 4 | 4-5 | 2 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 5 | 4-5 |
| T/C 50/50 | 30/1 | D377 | 5 | 4-5 | 4-5 | 4 | 5 | 3 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 4-5 | 4 | 3-4 |
| T/C 50/50 | 30/1 | S378 | 4-5 | 4-5 | 4-5 | 4 | 5 | 3 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 5 | 4 |
| T/C 50/50 | 30/1 | M380 | 4-5 | 4-5 | 4-5 | 4 | 5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 5 | 5 |
| T/C 50/50 | 30/1 | M381 | 5 | 4-5 | 4-5 | 4 | 5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 5 | 5 |
| T/C 50/50 | 30/1 | S382 | 4-5 | 4-5 | 4-5 | 4 | 4-5 | 3 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 5 | 5 |
| T/C 50/50 | 30/1 | D384 | 5 | 5 | 5 | 4 | 5 | 4 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 3-4 |
| T/C 50/50 | 30/1 | D385 | 4-5 | 4-5 | 4-5 | 4 | 5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 5 | 3-4 |
| T/C 50/50 | 30/1 | L386 | 4-5 | 4-5 | 4-5 | 4 | 5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 5 | 5 |
| T/C 50/50 | 30/1 | L387 | 4-5 | 4-5 | 4-5 | 4 | 5 | 5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 5 | 4 |
| T/C 50/50 | 30/1 | L388 | 4-5 | 5 | 5 | 4 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 4-5 |
| T/C 50/50 | 30/1 | L389 | 4-5 | 4-5 | 4-5 | 4 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 |
| T/C 50/50 | 30/1 | S390 | 4-5 | 4-5 | 4-5 | 4 | 4-5 | 2-3 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 5 | 5 |
| T/C 50/50 | 30/1 | D391 | 4-5 | 4-5 | 4-5 | 4 | 4-5 | 3 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 5 | 4-5 |
| T/C 50/50 | 30/1 | D392 | 4-5 | 4-5 | 4-5 | 4 | 4-5 | 3 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 5 | 4-5 |
| T/C 50/50 | 30/1 | S394 | 4-5 | 4-5 | 4-5 | 4 | 4-5 | 2-3 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 5 | 3 |
| T/C 50/50 | 30/1 | D395 | 5 | 4-5 | 4-5 | 4 | 5 | 4-5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 |
| T/C 50/50 | 30/1 | M396 | 4-5 | 4-5 | 4-5 | 4 | 5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 5 | 5 |
| T/C 50/50 | 30/1 | M397 | 4-5 | 4-5 | 4-5 | 4 | 5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 5 | 5 |
| T/C 50/50 | 30/1 | D398 | 5 | 4-5 | 4-5 | 4 | 5 | 3 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 |
| T/C 50/50 | 30/1 | D399 | 5 | 5 | 5 | 4 | 5 | 3-4 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 4-5 |
| T/C 50/50 | 30/1 | D400 | 5 | 5 | 5 | 5 | 5 | 2-3 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 5 | 4 |
| T/C 50/50 | 30/1 | S404 | 5 | 5 | 5 | 4 | 4 | 2 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 5 | 5 |
| T/C 50/50 | 30/1 | L405 | 4-5 | 5 | 5 | 4 | 5 | 5 | 4-5 | 5 | 5 | 4-5 | 5 | 5 | 4-5 | 5 | 5 | 4-5 | 5 | 4-5 |
| T/C 50/50 | 30/1 | L406 | 4-5 | 5 | 5 | 4 | 5 | 4-5 | 4-5 | 5 | 5 | 4-5 | 5 | 5 | 4-5 | 5 | 5 | 4-5 | 5 | 4 |

「染色堅牢度規格」

| 商品名 | 番手 | カラーナンバー | JIS L 0844 (洗濯) A-2号 | | | JIS L 0842 (耐光 注1) | JIS L 0849 (摩擦) | | JIS L 0848 (汗・酸性・アルカリ性) | | | | | | JIS L 0846 (水) | | | JIS L 0888 (汗・耐光複合) B法 | | | | |
|-----------|------|---------|----------------------|--------|--------|-----------------------|-----------------|-----|-------------------------|--------|--------|-------|--------|--------|----------------|--------|--------|------------------------|-------------|-----|-----|-----|
| | | | 変退色 | 汚染 (綿) | 汚染 (絹) | | 乾燥 | 湿潤 | 酸性 | | | アルカリ性 | | | 変退色 | 汚染 (綿) | 汚染 (絹) | 変退色 (酸性) | 変退色 (アルカリ性) | | | |
| | | | | | | | | | 変退色 | 汚染 (綿) | 汚染 (絹) | 変退色 | 汚染 (綿) | 汚染 (絹) | | | | | | | | |
| T/C 50/50 | 30/1 | D407 | 4-5 | 5 | 5 | 3-4 | 5 | 4-5 | 4-5 | 5 | 5 | 4-5 | 5 | 5 | 4-5 | 5 | 5 | 4-5 | 5 | 5 | 4-5 | 4-5 |
| T/C 50/50 | 30/1 | L408 | 4-5 | 5 | 5 | 3-4 | 5 | 4-5 | 4-5 | 5 | 5 | 4-5 | 5 | 5 | 4-5 | 5 | 5 | 4 | 5 | 5 | 4 | 4 |
| T/C 50/50 | 30/1 | L409 | 4-5 | 5 | 5 | 3-4 | 5 | 5 | 4-5 | 5 | 5 | 4-5 | 5 | 5 | 4-5 | 5 | 5 | 3 | 5 | 5 | 3 | 3-4 |
| T/C 50/50 | 30/1 | M410 | 4-5 | 5 | 5 | 4 | 5 | 4-5 | 4-5 | 5 | 5 | 4-5 | 5 | 5 | 4-5 | 5 | 5 | 4 | 5 | 5 | 4 | 3-4 |
| T/C 50/50 | 30/1 | L411 | 4-5 | 5 | 5 | 4 | 5 | 4-5 | 4-5 | 5 | 5 | 4-5 | 5 | 5 | 4-5 | 5 | 5 | 4 | 5 | 5 | 4 | 4-5 |
| T/C 50/50 | 30/1 | L412 | 4-5 | 5 | 5 | 3-4 | 4-5 | 4-5 | 4-5 | 5 | 5 | 4-5 | 5 | 5 | 4-5 | 5 | 5 | 4 | 5 | 5 | 4 | 3-4 |
| T/C 50/50 | 30/1 | L413 | 4-5 | 5 | 5 | 3-4 | 5 | 4-5 | 4-5 | 5 | 5 | 4-5 | 5 | 5 | 4-5 | 5 | 5 | 4 | 5 | 5 | 4 | 4 |
| T/C 50/50 | 30/1 | D414 | 4-5 | 5 | 5 | 4 | 5 | 4-5 | 4-5 | 5 | 5 | 4-5 | 5 | 5 | 4-5 | 5 | 5 | 4-5 | 5 | 5 | 4-5 | 3-4 |
| T/C 50/50 | 30/1 | L415 | 4-5 | 5 | 5 | 3-4 | 5 | 4-5 | 4-5 | 5 | 5 | 4-5 | 5 | 5 | 4-5 | 5 | 5 | 4-5 | 5 | 5 | 4-5 | 4-5 |
| T/C 50/50 | 30/1 | M416 | 4-5 | 5 | 5 | 4 | 5 | 4-5 | 4-5 | 5 | 5 | 4-5 | 5 | 5 | 4-5 | 5 | 5 | 4 | 5 | 5 | 4 | 3-4 |
| T/C 50/50 | 30/1 | CT-1 | 4-5 | 5 | 5 | 4 | 5 | 2-3 | 4-5 | 4-5 | 4-5 | 4-5 | 4-5 | 4-5 | 4-5 | 4-5 | 4-5 | 4 | 5 | 4-5 | 4 | 3-4 |
| T/C 50/50 | 30/1 | CT-10 | 4-5 | 4-5 | 4-5 | 3-4 | 4-5 | 2-3 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 5 | 4-5 | 4-5 | 4 | 5 | 4-5 | 4-5 | 4 |

注1：紫外線カーボンアーク灯光 第3露光法